DataACK Disable

NOT REQUIRED for Ham Radio Repeaters
Should not be ticked.

From Anytone

When the radio is monitoring the Mototurbo commercial repeaters, the radio will make a transmit to the repeater even if they select " TX prohibit", then the radio will freeze after doing a transmission to the repeater.

So we added the "DataACK Disable" option, the radio will not respond to the repeater.

Turn ON and OFF in each channel

http://tiny.cc/AnytoneDMR